

TO: John R. Pendergast
Senior Counsel

Phone: 216 839-7801
Mobile: 216 577-1920
john.pendergast@basf.com
Postal Address:
BASF Corporation
23700 Chagrin Blvd.
Beachwood, OH 44122

BASF - The Chemical Company
www.basf.com/usa

From "Kelly Coleman" <kelly@teammoneytrees.com>

08/01/2010 01:54 PM

Hi John,

A few photos of house interior that show the progression, if you compare them to others I have supplied , it is obvious that the rainy season is accelerating the interior damage.

The entire house is beginning to smell moldy and the pink and black bleed through in some places, is an indication that there is mold and mildew building up inside the walls. I state this from past history before the BASF sealant was installed as water-proofing which stopped all the water infiltration through brick joints until the sealant began to crack and fall out.

The first photo of a guy in shorts is not me , it is a guy who does some work for me, from time to time and this photo was not taken at the home, it was a project we were working on and Cheryle snapped a photo of Richard, for reasons unknown. This photo should not have been included in the dozen or so photos supplied herein, but in press of time, on Sunday, I did not bother to go back, through the process to delete it.

I submit these current photos in hopes that it will help with the need to reach a resolution .

yours truly,

Kelly

Kelly R Coleman

[attachment "BASF House interior 8-1-10.docx" deleted by John Pendergast/EB-NAFTA/BASF]